						160	1500
EPA REGION V							
	ORK OR	DER / REPORT			,		
SITE NAME: Sa	3		DATE 6	119 1	95		
SITE/SPILL NO.: 4U ON-SCENE COORDINATOR:				CONTRACT NO.:			
Sum Borris				RESPONSE MANAGER:  Ken Blain			
MONITORS:				CONTRACTOR:			
WORK AUTHORIZED				WORK ACCOMPLISHED			
1- Excavate exploration pito				1- Postpond, began Scrabi			
pipeline to evaluate the need for				12" of Sun	face So	1	
	- heate	the re	el for				
a formier Wal	Z	<del></del>					
2- EXCAUATE, IF WARANTED BY				2. Dela	yed		
THISK # 1, THE	<b></b>	, 					
IN THE PRES	ENCE	OF E	xplokes	r			
REP AT SITE							
3- grack The clean don't best was 3. Complete							
on-to H Six	<u>e.                                    </u>		5.5			<del></del>	
4. Strockpile clear det near				4- Del	ryed		
the nurtheast Corner.							
5) Mube do site for 10:00 Am				6- Com	alite.		
Startup							
·							
OSC_SIGNATURE RM SIGNATURE / OSC SIGNATURE RM/SIGNATURE							
S B O A B I S B O B BM							
Cam Nam	-9	n pr	<del>2</del>	Sam Jour	<del></del>	-Ou	7
AUTHORIZED PERSONNEL							
SUPERVISOR CERK FOREMAN PERATOR					CLEAN-UP T	//	
CHEMIST			OTHER		OTHER		
EQUIPMENT AND MATERIALS							
ITEM	YTITHAUD	USED	NOTUSED	ITEM	QUANTITY	USED	NOTUSED
2800 5/L T. Hee		✓		Fax Machin	,		
455 JD Loade	MB	4		Copie	1		
655 JD Loader	,			H.H. Radios	A		
780 Cupe Back hop	MB			Johnnies	2		
Plu Truck	2			D6-DOZER		<u></u>	
10x90 OFF. Tpala							
10x 40 SHOWN Truite				<u> </u>			
			AMENDME	-N12			
OSC SIGNATURE				RM SIGNATURE			l
SO SIGNATURE				LIM SIGNATIONE	•		1